Message

From: McClintock, Katie [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=2D5346D5556D4911A85E6AC0501C65DB-MCCLINTOCK, KATIE]

Sent: 10/29/2019 10:55:49 PM

To: Edward Kowalski [Kowalski.Edward@epa.gov]

Subject: FW: EPA Air Compliance Inspection Report, Hilcorp Alaska LLC, MPU **Attachments**: Air Compliance Inspection Report_Hilcorp_MPU_7-17-19.pdf

FYI



Katie McClintock Section Chief

Air Toxics and Enforcement Section

Enforcement and Compliance Assurance Division

U.S. EPA Region 10 1200 Sixth Ave, Suite 155 Mail Code 20-C04 Seattle, WA 98101 Phone: (206) 553-2143

From: Pavitt, John <Pavitt.John@epa.gov> Sent: Tuesday, October 29, 2019 3:29 PM

To: jupotter@hilcorp.com

Cc: McClintock, Katie <McClintock.Katie@epa.gov>; Williams, Christopher <Williams.Christopher@epa.gov>; Olds, Jason R (DEC) <jason.olds@alaska.gov>; Howard, Breanna K (DEC)

Sreanna.howard@alaska.gov>; Mallinger, Hunter L (DEC)

<hunter.mallinger@alaska.gov>

Subject: EPA Air Compliance Inspection Report, Hilcorp Alaska LLC, MPU



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 155 Seattle, Washington 98101-3188

ENFORCEMENT & COMPLIANCE ASSURANCE DIVISION

Julieanna Potter (Orczewska) Environmental Specialist – Air Quality Hilcorp Alaska, LLC

Re: Clean Air Act Compliance Evaluation Inspection at the Hilcorp Alaska, LLC, Milne Point Unit, AK

Dear Ms. Potter:

On July 17, 2019, the United States Environmental Protection Agency (EPA) conducted a compliance inspection at your facility along with the Alaska Department of Environmental Conservation (ADEC). The

purpose of the inspection was to determine compliance with the Clean Air Act (CAA), specifically, with New Source Performance Standards (NSPS), Subpart OOOOa – Standards of Performance for Crude Oil and Natural Gas Facilities. A copy of the inspection report is attached to this email. Please review the inspection report, note the areas of concern, and take any actions necessary to ensure compliance with the CAA.

An EPA Compliance Officer will use this inspection report in evaluating your facility's compliance with the CAA. This may result in subsequent contact from EPA personnel if a violation is identified. This message is sent only to transmit the inspection report, and it should not be interpreted as a final compliance determination. Please direct any questions regarding the compliance evaluation to me at pavitt.john@epa.gov.

Thank you for the cooperation and assistance extended to EPA and State personnel during the inspection.

Sincerely,

John Pavitt, Air Compliance Inspector Air and Toxics Enforcement Section U.S. EPA Region 10 Alaska Operations Office Anchorage, AK Phone: (907) 271-3688

Attachments:

1. Inspection Report